



Commercial Painting &  
Wall Covering Contractors

**PEAK  
PERFORMANCE**

## The Project: Harco labs

This manufacturing metal building was peeling extensively and lacked exterior protection.



### The Challenge:

The company's metal building exterior was peeling extensively. The previous paint contractor did not prepare the metal surface properly and applied the wrong paint for the surface.

### The Peak Performance:

Prepared the surface for adhesion of the proper coating. After power sanding an acrylic primer/finish system was applied to insure proper adhesion and durability. In its fourth year the building looks as good as the day it was painted.



### A Peak Customer:

Mr. Robert McCarthy, Facilities Director of Harco Labs: "We were painting every few years due to extensive paint peeling. K Morgan brought a true knowledge of metal buildings and the options open to us. They had to work in a busy parking lot with trucks and people all around. They also had to assure that the paint spray didn't cover area vehicles. We also had them paint areas inside the manufacturing facility where people and equipment are in the way. They were on time, on schedule, on budget and they were conscientious in their work. *We are extremely pleased with the work they did.*"

**Contact us to learn more about this project: 800.879.6990**